

Car Logo



2014 Harley-Davidson FLHXS

VIN Number **1HD1KRM18EB663770**

Report Date **08/09/2023**

Report ID **37433d4bda41b3808**

Vehicle Specifications

The specifications below are derived by decoding the VIN as provided by the manufacture.

Year 2014	Make Harley-Davidson	Model FLHXS	Body No data
Manufactured In UNITED STATES	Production SEQ 663770	Engine Type No data	Driveline No data
Anti-Break System No data	Steering Type No data	Tank No data	MPG City No data
MPG Highway No data	Standard Seating No data	Optional Seating No data	Length/Width/Hight (in.) No data/No data/No data
Transmission No data		Trim -	

Recall Information

This section contains information from National Highway Traffic Safety Administration Vehicle Safety. To find out if your vehicle still has open recalls that require repair, VINsmart recommends contacting an authorized dealer for more information.



Equipment

Recall #15V427000 Date: 07/06/2015

Summary

Harley-davidson motor company (harley-davidson) is recalling certain model year 2014-2015 road king (flhr), street glide (flhx), street glide special (flhxs), electra glide ultra classic (flhtcu), ultra limited (flhtk), police road king (flhp), police electra glide (flhtp), cvo ultra limited (flhtkse), 2014 cvo road king (flhrse), and 2015 electra glide ultra classic low (flhtcul), ultra limited low (flhtkl), road glide (fltrx), road glide special (fltrxs), cvo street glide (flhxse), and cvo road glide ultra (fltruse) motorcycles. The affected motorcycles have saddlebag mounting receptacles that may not adequately secure the saddlebags to the motorcycle.

Consequence

If a saddlebag is not adequately secured, it may separate from the motorcycle while riding, creating a road hazard and increasing the risk of a crash.

Remedy

Harley-davidson will notify owners, and dealers will replace the affected saddlebag mounting receptacles with updated receptacles, free of charge. The recall began on July 30, 2015. Owners may contact harley-davidson customer service at 1-800-258-2464. Harley-davidson's number for this recall is 0166.

Notes Owners may also contact the national highway traffic safety administration vehicle safety hotline at 1-888-327-4236 (tty 1-800-424-9153), or go to www.safercar.gov.

Power train:clutch assembly

Recall #15V216000 Date: 04/13/2015

Summary Harley-davidson motor company (harley-davidson) notified the agency on april 9, 2015, that they are recalling certain model year 2014-2015 electra glide ultra classic (flhtcu), electra glide ultra classic - twin cooled (flhtcu tc), ultra limited (flhtk), police electra glide (flhtp), street glide (flhx), street glide special (flhxs), cvo street glide (flhxse), 2015 electra glide ultra classic low (flhtcul), ultra limited low (flhtkl), electra glide ultra classic low - twin cooled (flhtcul tc), road glide special (fltrxs), road glide (fltrx), and 2014 cvo road king (flhrse) motorcycles. On july 31, 2015, harley-davidson expanded the recall to cover an additional 61,065 motorcycles. In the affected motorcycles, the clutch master cylinder may lose the ability to generate enough lift to disengage the clutch, especially if the motorcycle has been parked for an extended period of time.

Consequence When the engine is running and the motorcycle is in gear, if the clutch cannot be fully disengaged, the motorcycle may move unexpectedly, increasing the risk of a crash.

Remedy Harley-davidson will notify owners, and dealers will flush the clutch system and rebuild the clutch master cylinder, free of charge. The recall began april 23, 2015. Owners may contact harley-davidson customer service at 1-800-258-2464. Harley-davidson's number for this recall is 0165.

Notes Owners may also contact the national highway traffic safety administration vehicle safety hotline at 1-888-327-4236 (tty 1-800-424-9153), or go to www.safercar.gov.

Power train:clutch assembly

Recall #14V537000 Date: 09/05/2014

Summary Harley-davidson motor company (harley-davidson) is recalling certain model year 2014 electra glide ultra classic (flhtcu), ultra limited (flhtk), police electra glide (flhtp), street glide special (flhxs), street glide (flhx), tri glide ultra (flhtcutg), cvo limited (flhtkse), cvo road king (flhrse), cvo breakout (fxsbse), electra glide ultra classic twin cooled (flhtcutc), ultra limited shrine (flhtk shrine), street glide shrine (flhx shrine), and cvo softail deluxe (flstnse). In the affected motorcycles, a component in the clutch master cylinder may fail, reducing the pressure available to keep the clutch disengaged.

Consequence If the clutch does not remain disengaged, the motorcycle may creep forward while the rider intends to be stopped, increasing the risk of a crash.

Remedy Harley-davidson will notify owners, and dealers will rebuild the affected clutch master cylinders, free of charge. The recall began on september 17, 2014. Owners may contact harley-davidson customer service at 1-800-258-2464. Harley-davidson's number for this recall is 0159 & 0160.

Notes Owners may also contact the national highway traffic safety administration vehicle safety hotline at 1-888-327-4236 (tty 1-800-424-9153), or go to www.safercar.gov.

Service brakes, hydraulic

Recall #14V319000 Date: 06/12/2014

Summary Harley-davidson motor company (harley-davidson) is recalling certain model year 2014 abs-equipped touring and cvo touring motorcycles, models flhtk, flhtkse, flhtkshrine, flhtcu, flhtcutc, flhtp, flhx, flhxs, flhxshrine, flhr, flhrc, flhp, and flhrse, manufactured july 1, 2013, through may 7, 2014. The affected motorcycles may have been assembled with the front brake line positioned so that it can be pinched between the fuel tank and frame causing the front brake fluid pressure to increase.

Consequence A pinched brake line will increase the front brake fluid pressure, possibly resulting in a front wheel lock-up, increasing the risk of a crash.

Remedy

Harley-davidson will notify owners, and dealers will inspect the motorcycles for brake line damage and replace the damaged lines as necessary. Dealers will also install one or two cable straps to properly prevent the line from being pinched in the future, free of charge. The recall began on June 25, 2014. Owners may contact harley-davidson customer service at 1-800-258-2464.

Notes

Owners may also contact the national highway traffic safety administration vehicle safety hotline at 1-888-327-4236 (tty 1-800-424-9153), or go to www.safercar.gov.

Power train:clutch assembly

Recall #13V515000 Date: 10/17/2013

Summary

Harley-davidson motor company (harley-davidson) is recalling certain model year 2014 flhtcu, flhtk, flhtp, flhx, flhxs, flhtkse, and flhrse motorcycles manufactured May 3, 2013, through October 14, 2013. The clutch master cylinder may allow air into the clutch system. Additionally, the motorcycles may have been assembled with an incorrect clutch release plate. Either condition may prevent the clutch from disengaging.

Consequence

If the clutch does not disengage, the rider may have difficulty slowing or stopping the motorcycle, increasing the risk of a crash.

Remedy

Harley-davidson has already notified owners, and dealers will rebuild the clutch master cylinder and install the proper clutch release plate, as necessary, free of charge. The recall began in late October 2013. Harley-davidson's recall number is 0153. Owners may contact harley-davidson at 1-800-258-2464.

Notes

Owners may also contact the national highway traffic safety administration vehicle safety hotline at 1-888-327-4236 (tty 1-800-424-9153), or go to www.safercar.gov.

Disclaimer

VINsmart Disclaimer

VINsmart prepares its vehicle history and title reports based on data from government sources and independent agencies. VINsmart relies on its Data Sources for the accuracy and reliability of the information provided in its reports. VINsmart neither enters nor validates the data from its Data Sources, and does not guarantee the accuracy or completeness of the data provided.

Therefore, PLEASE BE ADVISED that (i) some state data pertaining to a VIN may not be contained in or available through any Data Source, (ii) some state data is provided to a Data Source via a daily, weekly or monthly format and therefore may not be current, (iii) some providers of data pertaining to a VIN (whether governmental or otherwise) may have failed to provide such data for incorporation into the Data Source, and (iv) neither VINsmart nor any Data Source has any control over the accuracy or completeness of data contained in any Data Source and none of them shall have any liability to any user or any third party concerning the quality, completeness or accuracy of any Data Source data.

Therefore, no responsibility is assumed by VINsmart or its agents for errors or omissions in this report. VINsmart further expressly disclaims all warranties, express or implied, including any implied warranties of merchantability or fitness for a particular purpose. This report may not be assigned or otherwise transferred, nor may the data be resold or otherwise transmitted, without the prior written permission of VINsmart in its absolute discretion.

If for any reason, a report we deliver does not have information from the applicable Data Source, we will gladly issue a credit towards your next vehicle history report, or refund your money, minus a \$2 processing fee, no questions asked. PLEASE NOTE: Canadian VINs, and chassis/incomplete vans or trucks will NOT be valued.

NHTSA - Recall Information Disclaimer

Regarding any history published or provided by VINsmart from the National Highway Traffic Safety Administration ("NHTSA") and/or the U.S. Department of Transportation ("DOT") with regard to a vehicle hereunder ("Recall History"), please be advised that VINsmart makes no claims, promises or guarantees about the accuracy, completeness, or adequacy of the Recall History and expressly disclaims liability for errors and omissions in the contents of the Recall History. No warranty of any kind, implied, expressed or statutory, including but not limited to the warranties of non-infringement of third party rights, title, merchantability, fitness for a particular purpose and freedom from computer virus, is given with respect to the contents of the Recall History. Reference in this Recall History to any specific commercial products, processes, or services, or the use of any trade, firm or corporation name is for the information and convenience of the public, and does not constitute endorsement, recommendation, or favoring by either VINsmart or NHTSA/DOT.

Trademark Disclaimer

The marks and third-party trademarks appearing in this report and their respective names, logos, emblems, slogans and vehicle model names and body designs are trademarks and/or service marks of their respective holders. Use of them does not imply any affiliation with or endorsement by them. Any reference by VINsmart to third-party trademarks is to identify the corresponding third-party goods and/or services and shall be considered nominative fair use under the trademark law.